

Date: 6/26/2025

Region: 4A

FEMS No.: 3156278

FAC ID: NY065

Maximo WO No.: 18792

Asset #: NA

Priority: Routine



Original Work Request:

Repair refrigerator in kitchen. Advant EDGE refrigerator emitting high pitch noise. The display shows error code "CL" indicating condenser coil is due for cleaning.

Description of Repairs Needed:

Labor and material to perform recommended service on Advant Edge refrigerator with error code. Checked wiring connections, cleaning coils, making necessary adjustments for proper operation. Clean up area and properly dispose of all spent materials.

Labor:	Labor Hrs	Labor Rate	Total
Service Technician	8	\$ 100.00	\$ 800.00
			\$ -

Material List:	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 800.00	\$ -	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$800.00	\$96.00	\$48.00	\$944.00

HUNOLD CONTRACTING INC.
72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
6/24/25

Quantity	Description	Amount
1	FEMS 3156278, WO 18792, NY065 Tonawanda, NY Perform recommended service on Advant Edge refrigerator with error code. Check wiring connections, clean coils, make any necessary adjustments for proper operation. Clean up and properly dispose of spent materials. Material: (Unknown at this time.) Labor: (8 hours @\$100/ hr.) = \$800	800.00
		Sub total 800.00
		Sales Tax N/A
		Total 800.00

Signature_____ Date_____

Signature_____ Date_____