



# INVOICE

CMI Management  
Mr. Joe Bayne  
5285 Shawnee Rd.  
Alexandria, VA. 22312

April 9, 2020

RE  
CSS# 24577 NY116 New Windsor  
AFRC HVAC# 4 in the first floor  
mechanical room  
is leaking water from a supply  
line.

- Isolate compromised fitting.
- Remove fitting (s) as necessary and replace.
- Remove and re-install existing pipe insulation.
- check for leaks.

1 Misc copper fittings and solder

Total. 1212.00

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email [rdpostulka@verizon.net](mailto:rdpostulka@verizon.net)

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL