

Over and Above Estimate

PA050 Indiana	CSS #11395.1 CMI #2636 – A) Hanging Hot Water Heater – Asset #6939
Description of Repairs	Labor and material to remove and replace Actuators.
Diagnosis: Initial Work Order	Site review determined that actuators are bad and not driving open or close.
Explanation of Additional Costs for Repairs	Excludes any system programming if required.
Additional Labor Cost to Perform Repairs	\$ 294.00 (Labor Rate \$98.00 x 3hrs = \$294.00)
Additional Material Cost to Perform Repairs	\$ 169.75 (Material quote for Schneider attached) Seven day delivery
Shipping (Standard)	\$ 24.00
Total Cost of Repair	\$ 487.75