

Over and Above Estimate

PA050 Indiana	CSS #11395.2 CMI #2636 – B) Room 110 – Asset #4431
Description of Repairs	Labor and material to remove and replace Control Board
Diagnosis: Initial Work Order	Site review determined that Control Board is non operable.
Explanation of Additional Costs for Repairs	NA
Additional Labor Cost to Perform Repairs	\$ 294.00 (Labor Rate \$98.00 x 3hrs = \$294.00)
Additional Material Cost to Perform Repairs	\$ 575.23 (Material quote attached) Five day delivery
Shipping (Standard)	\$ 24.00
Total Cost of Repair	\$ 893.23