

Four out of the five heaters in the BMA cannot be used due to cracked heat exchangers. Repair heaters as soon as possible or provide alternate source of heat if lead time on parts runs too far into heating season. Have recently had overnight temperatures in the low 40s.

Option 2: Replace the failed units w/4 new Reznor Heaters

CMI Cost Estimate								
Over & Above								
PA017 Clearfield								
Replace the failed units w/4 new Reznor Heaters								
CSS #15760 - CMI # 5904								
Prepared By: J. Bayne								
11.19.18								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
Replace the failed units w/4 new Reznor Heaters								
1. Repair Cost								
1.1 Labor	\$ 80.00	32						\$ 2,560.00
1.2 (4) Heat Exchangers					\$ -	\$ -	\$ -	\$ 4,475.32
1.3 Misc Fittings								\$ 500.00
Sub Total Repair Cost								\$ 7,535.32
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 80.00	2						\$ 160.00
CE Factor 102%								\$ 153.90
Grand Total								\$ 7,849.22