

Over and Above Estimate

Region: 2

Location: NY 116

CSS #: 18029

Maximo Work Order No.: 3197

Date Issued: 7/23/19

Original Description:

bay door doesn't work right also need all 4 door bottom rubber replaced.

Repairs Needed: Furnish and Install materials listed below to Repair, Service and adjust Motorized

Rolling Doors

Asset Number:

Quantity	Line Item Number	Description	Labor Hours	Shipping	Labor	Materials	Tax	Total
		See proposal						

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Tax and shipping	Total Cost	CE Factor	Total Estimate
8hr @274.00/HR	\$2,192.00	\$2,447.00	N/A	\$4,639.00	90%	\$4,175.10

Note: Tax and shipping are included in the materials cost