

Date: 10-31-23

Region: 4A

CSS No.: 95503

FAC ID: PA027

Maximo WO No.: 14274



Asset #: [ ]

Priority: [ ] 3

**Original Work Request:**

Repair the Reznor heater located in the large bay. The unit is not turning on when the thermostat is turned on.

**Description of Repairs Needed:**

Blower motor needs replacing on Reznor Heater

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -

**Material List:**

	Quantity	Cost	Total
Reznor Motor (147571), 115V 1/20HP 1050	1	\$ 475.79	\$ 475.79
Freight	1	\$ 75.00	\$ 75.00
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$350.00	\$550.79	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$900.79	\$108.09	\$54.05	\$1,062.93