

Date: 12-04-23

Region: 4A
FAC ID: PA027

CSS No.: 95970
Maximo WO No.: 14531

Asset #:

Priority: 3



Original Work Request:

Repair the fire alarm. The fire system alarm goes off everyday at approximately 1030, fault is TBL Ground Fault Loop 1.

Description of Repairs Needed:

Labor to investigate and troubleshoot fire alarm ground fault on Loop 1 at PA027. Crew will follow and trace out wire on fire alarm wiring loop 1. Crew will attempt to determine location of ground fault and repair it same day if able. Should site visit reveal that additional repairs are needed, a separate, future visit will be required to correct the outstanding deficiencies. If this is required, Grunua will provide a second, separate proposal for that final visit.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 144.00	\$ 1,152.00
Tech (2)	8	\$ 144.00	\$ 1,152.00

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$2,304.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,304.00	\$276.48	\$138.24	\$2,718.72