

Date:

Region:   
FAC ID:

CSS No.:   
Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

Motor pool gate operator is not working and there is oil leaking from the operator box. This is causing the gate to not close properly.

**Description of Repairs Needed:**

Proposal is to diagnose and repair if possible the Motor Pool Gate Operator as per the description of issues provided.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 95.00	\$ 1,520.00
Administrative	1	\$ 100.00	\$ 100.00

**Material List:**

	Quantity	Cost	Total
Hose kit (3 hoses) slide driver	1	\$ 303.56	\$ 303.56
Hydraulic oil	1	\$ 122.21	\$ 122.21
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$1,620.00	\$425.77	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,045.77	\$245.49	\$122.75	\$2,414.01