

Date: 7-10-25

Region: 4A

FEMS/CSS No.: 2966233

FAC ID: PA027

Maximo WO No.: 19536

Asset #:

Priority: 2



**Original Work Request:**

IDS system is non-functional and can't be repaired. IDS System for the vault needs to be repaired by upgrading if facility loses power the system will be down and soldiers will need to have guards posted 24/7. The following is what is needed for the system to be functional: mother board, cellular network card, zone expansion module, audio module, speaker/mic, keypad degree motion sensors, 12V 7AH batteries.

**Description of Repairs Needed:**

Proposal is for additional labor encountered due issues directly associated and accountable to Ft. McCoy. After system was installed, it was discovered that Ft. McCoy had connectivity issues due to not having current revisions of software needed to download the new installations. It was later discovered that the Ft McCoy programmer did not have Admin rights to the program w/ the new laptop. Proposal is for additional labor encountered with no upcharge for weekend spent in hotel, overtime or additional travel.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	80	\$ 95.00	\$ 7,600.00
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$7,600.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$7,600.00	\$912.00	\$456.00	\$8,968.00