

Date: 2-06-2025

Region: 4A

FEMS/CSS No.: 2966234

FAC ID: PA027

Maximo WO No.: 17996

Asset #:

Priority: 3



Original Work Request:

Exterior lights on outside of facility needs repaired. Training Bldg: entrance light, entry alcove light need to have bird nest removed and caging placed over the fixture, exterior light on left near the MEP fence and the light over the Mechanical Room door needs repaired. OMS man door on the back side needs to be repaired.

Description of Repairs Needed:

Vendor to replace wall pack lights on building, bucket lift required.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 81.25	\$ 650.00
		\$	-
		\$	-

Material List:

	Quantity	Cost	Total
small wall pack adjustable wattage	2	\$ 165.00	\$ 330.00
large adjustable wattage wall pack	2	\$ 275.00	\$ 550.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
Bucket Truck	1	\$ 1,000.00	\$ 1,000.00
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$650.00	\$880.00	\$1,000.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,530.00	\$303.60	\$151.80	\$2,985.40