

Date: 1-27-25

Region: 4A

FAC ID: PA027

FEMS/CSS No.: 3030930

Maximo WO No.: 17955

Asset #:

Priority: 2



Original Work Request:

Replace hydraulic pump for gate motor for the MEP gate

Description of Repairs Needed:

Replace hydraulic pump on Motor Pool Gate Operator

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 95.00	\$ 1,520.00
Administrative	1	\$ 100.00	\$ 100.00
			\$ -

Material List:

	Quantity	Cost	Total
Hydraulic Pump	1	\$ 798.32	\$ 798.32
8" Drive Wheel	1	\$ 487.71	\$ 487.71
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$1,620.00	\$1,286.03	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,906.03	\$348.72	\$174.36	\$3,429.12