

Date: 8/4/2023

Region: 4A
FAC ID: PA035

CSS No.: 93240
Maximo WO No.: 12773

Asset #:

Priority: 3



Original Work Request:

Repair battery for fire alarm at Firelite Emergency Comand Center (Voice Evac) next to FACP.

Description of Repairs Needed:

Replace batteries identified in Fire Systems Inspection Report as deficient. Batteries located on the Firelite Power Supply near the FACP. Batteries will be replaced with new per proposal

Labor:

	Labor Hrs	Labor Rate	Total
1 Tech	6	\$ 144.00	\$ 864.00
			\$ -

Material List:

	Quantity	Cost	Total
12V 40AH batteries	2	\$ 180.00	\$ 360.00
Shipping/Handling	1	\$ 75.00	\$ 75.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$864.00	\$435.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,299.00	\$155.88	\$77.94	\$1,532.82