

Date: 10-19-23

Region: 4A  
FAC ID: PA035

CSS No.: 95264  
Maximo WO No.: 14100

Asset #: [ ]

Priority: 3



**Original Work Request:**

The air compressor keeps starting and shutting off constantly. Repair possible leak in air system on compressor. Air compressor is not maintaining air pressure.

**Description of Repairs Needed:**

Investigated leak found at the SnapOn hose reel. Unable to fix leak and notified site staff to check for warranty since reel is SnapOn product. If not under warranty, will need to replace.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1) investigate	2	\$ 148.00	\$ 296.00
			\$ -

**Material List:**

	Quantity	Cost	Total
Trip Charge	51	\$ 1.00	\$ 51.00
Fuel Charge	1	\$ 9.18	\$ 9.18
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$296.00	\$60.18	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$356.18	\$42.74	\$21.37	\$420.29