

Date:

Region:   
FAC ID:

CSS No.:   
Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

Repair MEP fence. Physical Security Inspection failed due to the following: 4 foot area of fencing on the MEP by the gate is aluminum ties and they need to be steel

**Description of Repairs Needed:**

Replace aluminum ties with steel ties

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	2	\$ 70.00	\$ 140.00
Service Call	1	\$ 105.00	\$ 105.00

**Material List:**

Materials (Steel Ties, bag of 100)	Quantity	Cost	Total
Materials (Steel Ties, bag of 100)	1	\$ 74.00	\$ 74.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$245.00	\$74.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$319.00	\$38.28	\$19.14	\$376.42