

Date: 4-9-26



Region: 4A

FEMS/CSS No.: 3432871

FAC ID: PA035

Maximo WO No.: 21677

Asset #:

Priority: 2

Original Work Request:

Louvers for the exhaust system for the CO2 monitor need to be repaired/replaced in the OMS

Description of Repairs Needed:

Proposal is to repair exhaust system for CO monitors in OMS

Labor:	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 90.00	\$ 1,440.00
			\$ -
			\$ -

Material List:	Quantity	Cost	Total
Fan	1	\$ 663.55	\$ 663.55
Ductwork	1	\$ 600.00	\$ 600.00
Contactora	1	\$ 334.80	\$ 334.80
Sealtight and fittings	1	\$ 42.00	\$ 42.00
Lot Wire	1	\$ 18.00	\$ 18.00
Joint 1/2 EMT Conduit and fittings	1	\$ 14.40	\$ 14.40
			\$ -

Equipment List:	Quantity	Cost	Total
Lift (Delivery and Pickup)	1	\$ 1,848.00	\$ 1,848.00
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,440.00	\$1,672.75	\$1,848.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,960.75	\$595.29	\$297.65	\$5,853.69