

Date: 4-2-26



Region: 4A

FEMS/CSS No.: 3433126

FAC ID: PA035

Maximo WO No.: 21485

Asset #:

Priority: 2

Original Work Request:

Repair urinal that is leaking from the back (left side) and repair sloan valve on the left side toilet. Both located in the men's latrine.

Description of Repairs Needed:

Proposal is to repair leaking urinal and sloan valve on toilet in men's latrine

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
2" PVC DWV hub and coupling	1	\$ 1.56	\$ 1.56
2" PVC DWV 90 degree hub/elbow	1	\$ 3.21	\$ 3.21
2" x 2" PVC DWV 90 degree hub long term elbow	1	\$ 5.14	\$ 5.14
Fernco 2" x 2" DWV Flexible PVC Coupling	1	\$ 6.56	\$ 6.56
2" PVC DWV spigot x FIPT Cleanout Adapter w/ plug	1	\$ 4.97	\$ 4.97
Misc (shop supplies, saw blades, sealant, etc)	1	\$ 25.00	\$ 25.00
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$350.00	\$46.44	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$396.44	\$47.57	\$23.79	\$467.80