

Date: 3-24-26



Region: 4A

FEMS/CSS No.: 3535938

FAC ID: PA035

Maximo WO No.: 21487

Asset #:

Priority: 2

Original Work Request:

Replace strobing light in the drill hall and (2) exterior building light on the right side of the Training Center.

Description of Repairs Needed:

Proposal is to replace the strobing light in the drill hall and 6 exterior building lights on Training Ctr. Received communication from RFOS (Scott Kawski) on 3/24 requesting to add four (4) additional exterior lights for a total of six.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	6	\$ 100.00	\$ 600.00
Tech (1)	6	\$ 100.00	\$ 600.00
			\$ -

Material List:

	Quantity	Cost	Total
High bay light, 31,600 lumens,VUE-A-UV-30L-40K8-M-UL-10V	1	\$ 129.99	\$ 129.99
LED Wall Pack/Photocell, 3370 lumen, NTW-A-WM-T3-3L-30K-U:-CS-P	6	\$ 67.99	\$ 407.94
freight	1	\$ 50.00	\$ 50.00
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
lift	1	\$ 750.00	\$ 750.00
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,200.00	\$587.93	\$750.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,537.93	\$304.55	\$152.28	\$2,994.76