

Date: 4-1-26



Region: 4A

FEMS/CSS No.: 3576735

FAC ID: PA035

Maximo WO No.: 21657

Asset #:

Priority: 2

Original Work Request:

Replace GFI outlet in the Mechanical Room that is needed for one instantaneous HW heater and the kitchen water heater. Also trim down the door to the gym as new floor matting was installed and the door will no longer open or close

Description of Repairs Needed:

Proposal is to trim door to gym to allow proper operation of opening/closing and replace GFI for water heaters

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	3	\$ 100.00	\$ 300.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
GFCI 15A	1	\$ 24.99	\$ 24.99
Handy BX Cover Dupl Cover	3	\$ 1.59	\$ 4.77
Blades (2005948)	2	\$ 41.99	\$ 83.98
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$300.00	\$113.74	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$413.74	\$49.65	\$24.82	\$488.21