

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

Repair the two unit heaters that have bad fan motors in the motor pool. The heaters are located on the mezzanine in the OMS bldg.

**Description of Repairs Needed:**

Replace fan motors with new motors and discard old motors. The project will require a lift to replace one of the fan motors. Exceptions/Exclusions: repair limited to scope and repairs described.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	7	\$ 100.00	\$ 700.00
			\$ -

**Material List:**

	Quantity	Cost	Total
Blower Motor (J31R04091)	1	\$ 323.83	\$ 323.83
Motor (9F0302260000)	1	\$ 395.73	\$ 395.73
Freight	1	\$ 100.00	\$ 100.00
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
Lift	1	\$ 650.00	\$ 650.00
			\$ -
			\$ -

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$700.00	\$819.56	\$650.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,169.56	\$260.35	\$130.17	\$2,560.08