

Date: 1-11-24

Region: 4A

CSS No.: 96050

FAC ID: PA062

Maximo WO No.: 14793

Asset #: []

Priority: 3



Original Work Request:

Repair/replace the existing In-Sink-Aerator garbage disposal. The unit will not turn on and has been determined the motor starter is not working and the parts are discontinued

Description of Repairs Needed:

Replace kitchen disposer with new unit

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 100.00	\$ 800.00
			\$ -

Material List:

	Quantity	Cost	Total
InSinkErator (SS 500 disposer)	1	\$ 4,466.89	\$ 4,466.89
InSinkErator (AS 101K-7, AquaSaver Control Center)	1	\$ 2,831.41	\$ 2,831.41
Miscellaneous	1	\$ 25.00	\$ 25.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$800.00	\$7,323.30	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$8,123.30	\$974.80	\$487.40	\$9,585.49