

Date: 11-27-23

Region: 4A

FAC ID: PA063

CSS No.: 95878

Maximo WO No.: 14513

Asset #:

Priority: 2



Original Work Request:

Heater in the Motor Pool Bay will not come on.

Description of Repairs Needed:

Replace motor and vent wheel. Lead time on parts 3-5 days and will need a lift to remove old unit and install the new parts.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 100.00	\$ 400.00
			\$ -

Material List:	Quantity	Cost	Total
Motor (163892)	1	\$ 529.60	\$ 529.60
Vent Wheel (43814)	1	\$ 118.37	\$ 118.37
Freight	1	\$ 50.00	\$ 50.00
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
Lift	1	\$ 601.74	\$ 601.74
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$400.00	\$697.97	\$601.74

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,699.71	\$203.97	\$101.98	\$2,005.66