

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

Replace vehicle exhaust hose in motor pool bay.

**Description of Repairs Needed:**

Remove old duct hose and Install new ducting hose in motor pool bay. Ducting hose only found in 50', 75' and 100' lengths. Will cut to fit.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -

**Material List:**

	Quantity	Cost	Total
3AXWS - Ducting Hose 5"- 50' Polyurethane (#2035-0500-2050)	1	\$ 1,347.74	\$ 1,347.74
shipping/freight	1	\$ 25.00	\$ 25.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$350.00	\$1,372.74	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,722.74	\$206.73	\$103.36	\$2,032.83