

Date: 4-2-24

Region: 4A
FAC ID: PA063

CSS No.: 97067
Maximo WO No.: 15236

Asset #:

Priority: 3



Original Work Request:

Repair the roll down kitchen serving door as it is not opening all the way up.

Description of Repairs Needed:

Investigate/repair kitchen door that is not opening all the way up. Ensure door is operational. Note that the current door is outdated and no parts available. Also not a fire door, will need to replace if a fire door is required. Per Scott, fire door not required.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2) - Investigate/repair door operation	1.25	\$ 239.00	\$ 298.75
Trip Service Charge	1	\$ 213.00	\$ 213.00

Material List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
EIS (Vehicle surcharge)	1	\$ 10.00	\$ 10.00
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$511.75	\$0.00	\$10.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$521.75	\$62.61	\$31.31	\$615.67