

Date: 11-06-24

Region: 4A
FAC ID: PA063

FEMS/CSS No.: 99115
Maximo WO No.: 16902

Asset #:

Priority: 3



Original Work Request:

Repair 3 outside lights on the training center - flag light, outside Rm 102 and Rm 125 (all three are in a row).

Description of Repairs Needed:

During investigation, Tech discovered that there are four lights that need replacing. Proposal is to replace the lights and photocells.

Labor:

	Labor Hrs	Labor Rate	Total
Labor (2)	9	\$ 100.00	\$ 900.00
			\$ -

Material List:

	Quantity	Cost	Total
Wall Pack Lights (C-WP-E-TR-SCCT Series)	4	\$ 109.99	\$ 439.96
Photocell (CCR-PHC Series, 120-277V)	4	\$ 13.99	\$ 55.96
S&H	1	\$ 50.00	\$ 50.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
Scissor Lift	1	\$ 749.50	\$ 749.50
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$900.00	\$545.92	\$749.50

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,195.42	\$263.45	\$131.73	\$2,590.60