

Date: 1-15-25

Region: 4A

FAC ID: PA063

FEMS/CSS No.: 2992684

Maximo WO No.: 17913



Asset #:

Priority: 3

Original Work Request:

Replace the exhaust fan for the mens and ladies bathroom found during PMs

Description of Repairs Needed:

Replace exhaust fan with like model.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 100.00	\$ 400.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Upblast Exhauster, 1 PH, 1/3 hp (ALX135-UD033EC)	1	\$ 1,300.00	\$ 1,300.00
shipping	1	\$ 50.00	\$ 50.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$400.00	\$1,350.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,750.00	\$210.00	\$105.00	\$2,065.00