

Date: 04-02-25

Region: 4A

FAC ID: PA063

FEMS/CSS No.: 3071171

Maximo WO No.: 18509



Asset #:

Priority: 2

Original Work Request:

Repair PTAC unit. PTAC unit in motor pool office (Rm 202) will not continue to run. It goes for a while and then needs to be reset for the heat to come back on.

Description of Repairs Needed:

Proposal is to replace the malfunctioning PTAC unit with like model.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 100.00	\$ 400.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
PTAC - PTH153J50AXXX	1	\$ 1,288.87	\$ 1,288.87
Galvanized Wall Sleeve (WS900QW)	1	\$ 101.92	\$ 101.92
Exterior Grill (SGK01B)	1	\$ 36.71	\$ 36.71
shipping	1	\$ 75.00	\$ 75.00
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$400.00	\$1,502.50	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,902.50	\$228.30	\$114.15	\$2,244.95