

Date: 01-14-26

Region: 4A

FEMS/CSS No.: 3071171

FAC ID: PA063

Maximo WO No.: 20310

Asset #:

Priority: 2



**Original Work Request:**

PTAC unit in motor pool office (Rm 202) will not continue to run. It goes for a while and then needs to be reset for the heat to come back on.

**Description of Repairs Needed:**

Proposal is to replace PTAC unit, start up and check for proper operation. Contractor notes 10 wk lead time for PTAC unit.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	2	\$ 170.00	\$ 340.00
Trip charge	1	\$ 50.00	\$ 50.00
Tech (2)	32	\$ 170.00	\$ 5,440.00
Trip charge	1	\$ 100.00	\$ 100.00

**Material List:**

	Quantity	Cost	Total
PTAC (RSHE09K34E7P)	1	\$ 3,910.00	\$ 3,910.00
Wall Sleeve	1	\$ 790.00	\$ 790.00
Louvered Grille	1	\$ 230.00	\$ 230.00
Room Front Cover	1	\$ 220.00	\$ 220.00
Wall Patch	1	\$ 150.00	\$ 150.00
Electrical Materials (wiring, nuts, shop supplies, etc)	1	\$ 90.00	\$ 90.00
Freight	1	\$ 250.00	\$ 250.00

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$5,930.00	\$5,640.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$11,570.00	\$1,388.40	\$694.20	\$13,652.60