

Date: 06-04-25

Region: 4A

FEMS/CSS No.: 3156193

FAC ID: PA063

Maximo WO No.: 19186

Asset #:

Priority: 3



Original Work Request:

Repair exhaust hose ends in VMS building. CMI Tech stated that we need 6" 90-degree angles for the exhaust system in the OMS Present ones are all rusted out. He is aware of the amount that is needed.

Description of Repairs Needed:

Proposal is to replace rusted out exhaust hose ends in VMS.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	2	\$ 100.00	\$ 200.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Exhaust Hose Ends (TPA-06-05)	1	\$ 299.99	\$ 299.99
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$200.00	\$299.99	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$499.99	\$60.00	\$30.00	\$589.99