

Date: 4-13-26



Region: 4A

FEMS/CSS No.: 3577034

FAC ID: PA063

Maximo WO No.: 21686

Asset #:

Priority: 3

Original Work Request:

Air compressor located on the mezzanine of the motor pool made a loud noise and it seemed the water separator blew.

Description of Repairs Needed:

Proposal is to replace the air compressor filter on the compressor located in the mezzanine of Motor Pool.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	2.5	\$ 100.00	\$ 250.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Filter 1" NPT, 160 cfm, 0.5 micron (M30-08-M00)	1	\$ 439.99	\$ 439.99
Misc (shop supplies, tape, rags, etc.)	1	\$ 20.00	\$ 20.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$250.00	\$459.99	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$709.99	\$85.20	\$42.60	\$837.79