

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST LIGHTING, OUTSIDE

SITE AND BLDG #:

P 096-01

LOCATION/RM #:


MGP

WO#

10739

ASSET #

7443

MECHANIC
SIGNATURE:


DATE:

9/29/18

START TIME:

0630

FINISH TIME:

0640

GENERAL INSTRUCTIONS		COMPLETION	
		YES	NO
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.		☒
2	Schedule and coordinate work with operating personnel.		☒
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.		☒
TO BE PERFORMED BY A QUALIFIED SERVICE PERSONNEL			
1	Open and tag switch.		☒
2	Inspect visual condition of wiring. Look for evidence of overheating.		☒
3	Check for proper light operation.		☒
4	Test operation of automatic switches/ time clock/ photocells if applicable.		☒
5	Inspect light pole and mounting devices for deficiencies.		☒
6	For any noted deficiency, take pictures and open corrective maintenance ticket.		☒

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes:

2 P Single

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST LIGHTING, OUTSIDE

SITE AND BLDG #: *Pa 096-01*MECHANIC
SIGNATURE: *[Signature]*DATE: *9/24/18*LOCATION/RM #: *MEB* WO# *10729*ASSET # *7461*START TIME: *0630*FINISH TIME: *0640*

ITEM NO.	DESCRIPTION	COMPLETION STATUS	
		YES	NO
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.		
2	Schedule and coordinate work with operating personnel.		
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.		
TO BE PERFORMED AT EACH INSPECTION VISIT			
1	Open and tag switch.		
2	Inspect visual condition of wiring. Look for evidence of overheating.		
3	Check for proper light operation.		
4	Test operation of automatic switches/ time clock/ photocells if applicable.		
5	Inspect light pole and mounting devices for deficiencies.		
6	For any noted deficiency, takes pictures and open corrective maintenance ticket.		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes:

5 PC

2 pole out is Bad Cos