

Date:

Region:
FAC ID:

CSS No.:
Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Repair fire alarm panel trouble codes. This facility continues to receive fire alarm notifications in both the AMSA and Wrehouse. The emails received indicate Trouble-Delay and Communication Failure Delay.

Description of Repairs Needed:

Investigate and repair trouble signal found on Notifier FACP. Tamper switch in Hydro Room needs adjusting and Knox Box showing open. Reset panel and adjust switch to return panel back to normal

Labor:

	Labor Hrs	Labor Rate	Total
1 Tech	6	\$ 144.00	\$ 864.00
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$864.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$864.00	\$103.68	\$51.84	\$1,019.52