

Date: 12-21-23

Region: 4A

CSS No.: 96063

FAC ID: PA118

Maximo WO No.: 14550

Asset #:

Priority:  2



**Original Work Request:**

Repair Co-Ray vac tube heater located in the warehouse. Co-Ray heater unit on right side of warehouse making a grinding noise when it is in operation.

**Description of Repairs Needed:**

Replace electrodes for Co-Ray heating unit to return back to operation.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -

**Material List:**

	Quantity	Cost	Total
CO-RAY Electrode (Part #02713200)	4	\$ 102.07	\$ 408.28
Freight	1	\$ 25.00	\$ 25.00
Misc supplies	1	\$ 25.00	\$ 25.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$350.00	\$458.28	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$808.28	\$96.99	\$48.50	\$953.77