

Date: 8-19-24

Region: 4A

CSS No.: 98568

FAC ID: PA118

Maximo WO No.: 16371



Asset #: [ ]

Priority: 2

**Original Work Request:**

Fire alarm control panel in the AMSA continues to go in alarm - error code is "Program Corrukpted". The fire alarm goes off every day as a reminder to repair the FACP. Picture attached - Fire Fighters will need to be contacted to perform the work as they installed the system originally and they will need to reprogram the FACP. Recommended Contractor: Fire Fighter Sales and Service

**Description of Repairs Needed:**

Technician to troubleshoot and reprogam the main fire alarm control panel

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	2	\$ 140.00	\$ 280.00
Truck Charge	1	\$ 140.00	\$ 140.00

**Material List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$420.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$420.00	\$50.40	\$25.20	\$495.60