

Date: 9-17-24

Region: 4A

FAC ID: PA118

CSS No.: 98888

Maximo WO No.: 16621

Asset #:

Priority: 1



Original Work Request:

The fire pump engine is losing water pressure somewhere in the building. Fire Dept was called out. Repair fire pump engine to maintain fire suppression system in the building.

Description of Repairs Needed:

USAR Conneaut fire pump emergency call to investigate operation of diesel fire pump. Determined excessive vehicle exhaust caused fire alarm condition. All fire and life safety components are back on line and in service.

Labor:

	Labor Hrs	Labor Rate	Total
Tech	3	\$ 144.00	\$ 432.00
Emergency Trip Charge	1	\$ 225.00	\$ 225.00
Labor - OT	2	\$ 216.00	\$ 432.00

Material List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$1,089.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,089.00	\$130.68	\$65.34	\$1,285.02