

Date:

Region:
FAC ID:

CSS No.:
Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Reznor type heater in the gym in the Warehouse (one on right) needs to be repaired. When it turns on it sounds like the bearings are going bad and makes a very loud noise.

Description of Repairs Needed:

Replace motor on heater and verify operations.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	1.5	\$ 100.00	\$ 150.00
			\$ -

Material List:

	Quantity	Cost	Total
motor (1/15HP Motor 96288)	1	\$ 85.00	\$ 85.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$150.00	\$85.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$235.00	\$28.20	\$14.10	\$277.30