

Date: 2-3-2025

Region: 4A

FEMS/CSS No.: 3030764

FAC ID: PA118

Maximo WO No.: 17980

Asset #:

Priority: 2



Original Work Request:

Warehouse has 8 infrared heater ignitors that are not working and there is one in bay 5 of the AMSA. This is urgent as there is limited heat in the warehouse.

Description of Repairs Needed:

Repair CoRay Vac system to provide heat to warehouse and AMSA.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1) - Initial Investigation	8	\$ 156.00	\$ 1,248.00
Trip Charge	1	\$ 95.00	\$ 95.00
Tech (1) - Repair	8	\$ 156.00	\$ 1,248.00
Trip Charge	1	\$ 95.00	\$ 95.00

Material List:

	Quantity	Cost	Total
Gas Valve (90032502)	1	\$ 480.00	\$ 480.00
Relay (RH3B)	1	\$ 32.00	\$ 32.00
Freight	1	\$ 80.00	\$ 80.00
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$2,686.00	\$592.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,278.00	\$393.36	\$196.68	\$3,868.04