

Date: 6-18-25

Region: 4A

FEMS/CSS No.: 3031057

FAC ID: PA118

Maximo WO No.: 19496

Asset #:

Priority:  2



**Original Work Request:**

Repair duct detector in the Cambridge MAU. The fire alarm is being set off whenever the MAU comes on the heat the building. The MAU has been checked and serviced and is burning clean.

**Description of Repairs Needed:**

Proposal is to replace existing compromisede Edwards duct detector on building fire alarm system

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 154.00	\$ 2,464.00
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
Photoelectric Duct Smoke Detector (Edwards SIGA-ST)	1	\$ 295.00	\$ 295.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$2,464.00	\$295.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,759.00	\$331.08	\$165.54	\$3,255.62