

Date: 2-7-2025



Region: 4A

FEMS/CSS No.: 3031117

FAC ID: PA118

Maximo WO No.: 18002

Asset #:

Priority: 2

Original Work Request:

Replace 100' oil hose for lube system. Balcrank Signature Series Premium - Model #2111-041, Serial #3/24/14, max fluid pressure with hose 300 psi. The hose is starting to leak in numerous places.

Description of Repairs Needed:

Replace oil hose for lube system

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	4.5	\$ 100.00	\$ 450.00
			\$ -
			\$ -

Material List:	Quantity	Cost	Total
1/2" Hyd hose	80	\$ 5.95	\$ 476.00
Hose End2	2	\$ 8.75	\$ 17.50
Misc	1	\$ 17.95	\$ 17.95
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$450.00	\$511.45	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$961.45	\$115.37	\$57.69	\$1,134.51