

Date: 7-25-25

Region: 4A

FEMS/CSS No.: 3189984

FAC ID: PA118

Maximo WO No.:

Asset #:

Priority: 3



Original Work Request:

Two air pressure regulator valves and gauges need to be replaced for the piping between bays 9 and 10 and between bays 6 and 7.

Description of Repairs Needed:

Replace pressure regulator valves and gauges as described in SOW

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	2.5	\$ 100.00	\$ 250.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Pressure Gauge (4FMC8)	2	\$ 15.00	\$ 30.00
Air Pressure Regulator, 3/4" (R28-06-F000B)	1	\$ 99.99	\$ 99.99
Air Pressure Regulator, 1/2" (R28-04-F000B)	1	\$ 94.99	\$ 94.99
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$250.00	\$224.98	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$474.98	\$57.00	\$28.50	\$560.48