

Date: 10-2-25



Region: 4A

FEMS/CSS No.: 3313641

FAC ID: PA118

Maximo WO No.: 20325

Asset #:

Priority: 2

Original Work Request:

The alarm box and emergency shut off for the 3K gal diesel tank at ECS 103 needs replacing. The alarm sensor is barely audible and the emergency shut off is functional, but the plastic button are breaking apart. The sensor alarm consol is manufactured by Franklin Fueling Systems, the specific alarm consol needed is the S940 sensor alarm console and the emergency stop is just a standard push button shut off.

Description of Repairs Needed:

Proposal is to replace the emergency stop button and alarm console on the 3,000 gal diesel fuel tank at ECS 103.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	6	\$ 100.00	\$ 600.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Alarm console (S940)	1	\$ 1,897.01	\$ 1,897.01
Emergency Stop (10250T5B62-71X)	1	\$ 202.96	\$ 202.96
Freight	1	\$ 22.95	\$ 22.95
Misc (conduit, wiring, shop supplies, etc.)	1	\$ 100.00	\$ 100.00
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$600.00	\$2,222.92	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,822.92	\$338.75	\$169.38	\$3,331.05