

Date: 3-10-26



Region: 4A

FEMS/CSS No.: 3497178

FAC ID: PA118

Maximo WO No.: 21482

Asset #:

Priority: 2

Original Work Request:

New notifier card for the main fire panel is needed to clear the dAP failure signals on the panel. Fire alarm panel continues to show trouble alarms.

Description of Repairs Needed:

Proposal is to install new high/low speed combo fiber card. Tech with Notifier programming software will program the new card into existing Notifier panel.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 154.00	\$ 1,232.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Notifier High/Low Speed Combo Fiber Card	1	\$ 3,993.00	\$ 3,993.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,232.00	\$3,993.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$5,225.00	\$627.00	\$313.50	\$6,165.50