

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST LIGHTING, OUTSIDE

SITE AND BLDG #: *Pa 161 - 01*LOCATION/RM #: *Pmhr* WO# *10851*ASSET *7356*MECHANIC
SIGNATURE: *[Signature]*START TIME: *630*DATE: *8/23/18*FINISH TIME: *640*

GENERAL INSTRUCTIONS		SPECIAL INSTRUCTIONS		REMARKS	
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.				
2	Schedule and coordinate work with operating personnel.				
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.				
4	Open and tag switch.				
5	Inspect visual condition of wiring. Look for evidence of overheating.				
6	Check for proper light operation.				
7	Test operation of automatic switches/ time clock/ photocells if applicable.				
8	Inspect light pole and mounting devices for deficiencies.				
9	For any noted deficiency, take pictures and open corrective maintenance ticket.				

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes:

10 *k* *Don Su*

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST LIGHTING, OUTSIDE

SITE AND BLDG #:

R 166 - C1

LOCATION/RM #:

R

WO# 10957

ASSET # 7357

MECHANIC

SIGNATURE:

START TIME:

DATE: 8/23/19

FINISH TIME:

630 640

GENERAL INSTRUCTIONS		CHECKS TO BE PERFORMED		COMMENTS	
NO.	DESCRIPTION	YES	NO		
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.				
2	Schedule and coordinate work with operating personnel.				
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.				
4	Open and tag switch.				
5	Inspect visual condition of wiring. Look for evidence of overheating.				
6	Check for proper light operation.				
7	Test operation of automatic switches/ time clock/ photocells if applicable.				
8	Inspect light pole and mounting devices for deficiencies.				
9	For any noted deficiency, take pictures and open corrective maintenance ticket.				

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

Additional Notes:

16

R

1 set of Doubles out