

Date: 7/14/2023

Region: 4A
FAC ID: PA209

CSS No.: 93742
Maximo WO No.: 13360

Asset #:

Priority: 3



Original Work Request:

Repair urinal in men's restroom. Urinal on the left is leaking behind the urinal when it is flushed and needs repaired.

Description of Repairs Needed:

Urinal is cracked and requires replacing.

Labor:

	Labor Hrs	Labor Rate	Total
1 Tech	2.5	\$ 100.00	\$ 250.00
			\$ -

Material List:

	Quantity	Cost	Total
Urinal - 6590.001.020 (WHT)	1	\$ 212.90	\$ 212.90
Shop Supplies	1	\$ 25.00	\$ 25.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$250.00	\$237.90	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$487.90	\$58.55	\$29.27	\$575.72