

Date: 11-17-23

Region: 4A
FAC ID: PA209

CSS No.: 95277
Maximo WO No.: 14106

Asset #:

Priority: 3



Original Work Request:

Repair 2 Weil McLain boilers as they have error codes for the flame fault. The flame rods will need to be replaced.

Description of Repairs Needed:

Investigate and repair Weil McLain boilers, including replacing flame rods.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1) - Investigate Only	3.5	\$ 148.00	\$ 518.00
Tech (1) - Repair	8	\$ 148.00	\$ 1,184.00

Material List:

	Quantity	Cost	Total
Trip Charge - Investigate	1	\$ 180.00	\$ 180.00
Trip Charge - Repair	1	\$ 180.00	\$ 180.00
Ignitor Kit w Transformer (384 000 200)	1	\$ 428.00	\$ 428.00
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,702.00	\$788.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,490.00	\$298.80	\$149.40	\$2,938.20