

Date: 8/7/2023

Region: 4A

FAC ID: PA209

CSS No.: 12768

Maximo WO No.: 93236

Asset #:

Priority: 3



Original Work Request:

Repair fire extinguisher Tag #11, Serial #NS-376041, Model Amerex 441, Size 10#, Type ABC

Description of Repairs Needed:

Replace 1 - 10lb ABC Extinguishers identified during fire system inspection for replacement.

Labor:	Labor Hrs	Labor Rate	Total
1 Tech	1.5	\$ 120.00	\$ 180.00
			\$ -

Material List:	Quantity	Cost	Total
10lb ABC Extinguishers	1	\$ 76.99	\$ 76.99
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$180.00	\$76.99	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$256.99	\$30.84	\$15.42	\$303.25