

Date: 8/8/2023

Region: 4A
FAC ID: PA209

CSS No.: 13432
Maximo WO No.: 94360

Asset #:

Priority: 2



Original Work Request:

Packaged Terminal Heat Pump (PTHP) located in Rm 106 of Maintenance Bldg is not working. Unit wil not turn on and no indicator light is showing on the unit. Repair to operate.

Description of Repairs Needed:

Investigate PTHP in Rm 106 for repair solution.

Labor:

	Labor Hrs	Labor Rate	Total
1 Tech	3.5	\$ 148.00	\$ 518.00
			\$ -

Material List:

	Quantity	Cost	Total
Fuel Charge	1	\$ 180.00	\$ 180.00
Truck Fee	1	\$ 50.00	\$ 50.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$518.00	\$230.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$748.00	\$89.76	\$44.88	\$882.64