

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Repair boiler #2 as we are getting an error code HW FLT control board. Tried resetting but still will not work.

Description of Repairs Needed:

Replace expansion board and verify operations.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	6	\$ 148.00	\$ 888.00
trip charge	1	\$ 180.00	\$ 180.00

Material List:

	Quantity	Cost	Total
Expansion Board (383-600-160) + freight	1	\$ 648.00	\$ 648.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,068.00	\$648.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,716.00	\$205.92	\$102.96	\$2,024.88