

Date: 6-10-24

Region: 4A
FAC ID: PA209

CSS No.: 97686
Maximo WO No.: 15597

Asset #:

Priority: 3



Original Work Request:

Repairs required from the fire inspection report. Replace two 12 VCD 55AH batteries and troubleshoot manual pull station that did not report to fire panel during testing. Perform hydrostatic test on piping on the fire department connection.

Description of Repairs Needed:

Proposal completing a 5-yr hydrostatic inspection of fire department connection while on site and installing (2) new 12VDC 55AH batteries to replace those existing that failed annual load test.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 144.00	\$ 1,152.00
			\$ -

Material List:

	Quantity	Cost	Total
12 vDC 55 AH batteries	2	\$ 216.00	\$ 432.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,152.00	\$432.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,584.00	\$190.08	\$95.04	\$1,869.12