

Date: 7-01-24

Region: 4A

CSS No.: 98242

FAC ID: PA209

Maximo WO No.: 15864



Asset #: [Redacted]

Priority: 2

Original Work Request:

Repair ACCU-1 unit. During initial visit it was discovered that ACCU-1 need contactors, refrigerant and a new fan blade and caging for the fan as it was damaged when the blade broke. (Follow up to CSS 98187)

Description of Repairs Needed:

Proposal to replace damaged motor, fan blade and contactor on ACCU-1 unit that was damaged when the blade broke on the unit. Includes replacing refrigerant and miscellaneous parts to return unit to operation.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	12	\$ 156.00	\$ 1,872.00
Trip Charge	1	\$ 360.00	\$ 360.00

Material List:

	Quantity	Cost	Total
Contactor (CTR2580)	1	\$ 44.00	\$ 44.00
Auxiliary (SFSWT03533)	1	\$ 9.00	\$ 9.00
Motor Support (SUP4746)	1	\$ 152.00	\$ 152.00
Fan Motor Slinger (SLG00032)	1	\$ 11.00	\$ 11.00
Controller (CNT2923)	1	\$ 74.00	\$ 74.00
R438A Refrigerant (50#)	1	\$ 960.00	\$ 960.00
Freight	1	\$ 160.00	\$ 160.00

Equipment List:

	Quantity	Cost	Total
Motor (5K19RN6261BS)	1	\$ 1,400.00	\$ 1,400.00
Fan Blade (FAN1516)	1	\$ 270.00	\$ 270.00
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$2,232.00	\$1,410.00	\$1,670.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$5,312.00	\$637.44	\$318.72	\$6,268.16